



10-1937 / 10-1946 / 10-1947 / 12-0110





PUMP IS PLACED INTO POSTION WITH GASKET AND HARDWARE, DELIBERATELY LEFT LOOSE. INSTALL #1 CAMSHAFT MAKING SURE ALIGNMENT PINS LOCATE WITHIN OIL PUMP ROTOR. ROTATE SHAFT UNTIL FREE.





TORQUE OIL PUMP HARDWARE TO 10 INCH LBS. WHILE CAMSHAFT IS IN PLACE. CAM SHAFT IN EFFECT IS ACTING AS AN ALIGNMENT TOOL.



10-1937 : REPLICA ULH CAM COVER 10-1946 : 45" CAM COVER NATURAL

10-1947: WR 45" CAM COVER ALLOY

49-0606: OIL FEED PUMP

9409-22 : OIL PUMP MOUNT KIT

49-0094 : FEED PUMP UPGRADE

12-0110: SIDE VALVE FEED PUMP KIT



10-1937 Cover



Note: 49-2562 is shown installed