



NOTES FOR PHOTOS: Modification to the right side engine case point "B", must be welded to build platform for the new stud location. Also point "A" on cam cover must be welded up and relocated. A WR cam cover is available, VT #10-1947 WR 45" Cam Cover Alloy. Magneto assembly should be screwed in place by 5/16" screws. Original right engine case and generator holes in cam cover must be enlarged to 5/16".



















