

**V-Twin MFG.
Hydraulic Sprocket Kit
FITS 1958-1961 BT
VT Part No. 19-0001**

This is a custom application and should only be installed by a knowledgeable and trained motorcycle technician.

V-Twin Mfg. accepts no responsibility for improper installation.

Technical Note:

The outer flange of the brake drum may require slight grinding for exact fit of the sprocket.

The 1958-1961 brake drums were mad from cast iron and the outer edge may be of various dimensions.