

V-Twin MFG

Upper Fairing Bracket Repair Kit

For use on 1979-up FLT Models

VT No. 31-0344

1. Remove the outer fairing
2. Remove the inner fairing screw
3. Place the appropriate repair bracket in place
4. Return the screw to original location (do not tighten completely)
5. Drill out the three holes
6. Place the supplied bolts and nuts in the drilled holes
7. Tighten the inner fairing screw
8. Install the outer fairing