

TC88 Chain Drive Cams for 1999-2006 Models Except 2006 FXD

			Duration				
Part#	Grind	Timing*	.053	.020	Valve Lift	Lift @ TDC	Springs
10-8121	TW21	10/30 40/08	220 228	255 264	.498 .498	.134 .121	Stock
10-8127	TW26a	11/35 41/09	226 230	262 266	.490 .490	.138 .112	Stock
10-8141	TW31s	10/46 52/08	236 240	272 276	.510 .510	.131 .120	Stock
10-8137	TW37b	18/38 46/14	236 240	272 276	.510 .510	.174 .148	Stock
10-8154	TW54	16/42 43/15	238 238	273 273	.555 .555	.165 .158	Hi-Lift
10-8150	TW50	20/48 54/18	248 252	283 287	.510 .510	.184 .168	Stock
10-8155	TW55	22/46 52/20	248 252	283 292	.550 .550	.197 .181	Hi-Lift
10-8151	TW60a	24/56 58/22	260 260	296 296	.560 .560	.205 .192	Hi-Lift

*Timing and duration listed for .053 cam lift