




1999-up Cam Shaft Component for TC-88



Cam Shaft Components for TC-88 models, 1999-up unless noted.

VT No.	OEM	#	Item
12-1178	601	1	Roll Pin
37-1000	765	1A	Plug
12-0750	9198	2	Left Side Cam Shaft Bearing 1999-05
12-0765	9215	2	As Above 2006-up
37-1001	3290	3	Cam Support Plate Plug 1999-05
9946-20	4740A	4	Allen Screw Set
37-1002	4741A	5	Screw
12-0751	8990A	7A	Ball Bearing 1999-05
12-0762	8983	8	Bearing 1999-05
12-0905	11031	8	Retaining Ring 1999-05
12-0766	942	8	Retaining Screw Chain Tensioner 2006-up
14-0814	11286	9	O-Ring 1999-05
14-0803	11293	10	O-Ring
14-0819	11298	11	O-Ring, Viton 1999-05
14-0820	11301	12	O-Ring 1999-05
12-0753	11494	13	Retaining Ring 1999-05
12-0767	11461	13	As Above 2006-up
12-0761	16589-99	13A	Dowel Ring
15-1214	17045-99	14	Cam Service Gasket Kit
12-0754	24623-99C	14A	Right Side Main Bearing 1999
12-0763	24604-00C	14A	As Above 2000-06
12-0768	24605-07	14A	As Above 2007-up
10-0900	25267-99B	15	Cam Support Plate Assy w/bearings, retaining plate, tensioner & bypass valve 1999-05
10-0907	25355-06	15	Cam Support Plate w/Bypass Valve 06-up
10-0901	25344-99	16	Crankshaft Bushing
15-1198	25244-99A	17	Cam Cover Gasket
10-0813	25247-99	18	Chrome Cam Cover
42-0702	25369-01A		Chrome Cam Cover, 2001-up
10-8178	25937-99A	19, 20	Cam Shaft Set 1999-05
10-0902	25562-99	21	Cam Drive Spacer, .350 1999-05
10-0903	25595-99	21	Cam Drive Spacer, .355 1999-05
10-0904	25674-99	21	Cam Drive Spacer, .360 1999-05
10-0905	25675-99	21	Cam Drive Spacer, .365 1999-05
10-0906	25676-99	21	Cam Drive Spacer, .370 1999-05
10-0908	25729-06	21	As Above .100 2006-up
10-0909	25731-06	21	As Above .110 2006-up
10-0910	25731-06	21	As Above .120 2006-up

10-0911	25736-06	21	As Above .130 2006-up
10-0912	25737-06	21	As Above .140 2006-up
10-0913	25738-06	21	As Above .150 2006-up
10-0480	25593-99	22	Cam Drive Sprocket, 34T 1999-05
10-0914	25728-06	22	As Above 2006-up
10-0481	25607-99	23	Secondary Cam Drive Chain 1999-05
10-0915	25683-06	23	As Above 2006-up
10-0482	25609-99	24	Crankshaft Sprocket, 17T 1999-05
10-0916	25673-06	24	As Above 2006-up
10-0483	25610-99	25	Primary Cam Drive Chain 1999-05
10-0917	25675-06	25	As Above 2006-up
12-0755	26035-99	26	Oil Pump Assembly Cpt 1999-05
12-0769	26037-06	26	As Above 2006-up
13-0180	26210-99	27	Relief Valve Spring
12-1418	26400-82B	28	Oil Pump Relief Valve
12-0756	26464-99	29	Pressure Geo-Rotor Assy 1999-05
42-0085	32543-99	32	Sensor Cover, Alloy
42-0119	32679-99	32	Sensor Cover, Chrome
10-0484	35052-99	33	Bearing Retaining Plate 1999-05
12-0760	35115-99	33A	Retaining Ring 1999-01
12-0764	35114-02	33A	Retaining Ring 2002-up
10-0485	39954-99	34	Primary Cam Drive Chain Tensioner 1999-05
10-0918	39968-06	34	As Above 2007-up BT, 2006-up FXD
10-0486	39964-99A	35	Secondary Cam Drive Chain Tensioner Late 1999-05 BT except 2006-up FXD
10-0919	39969-06	35	As Above 2007-up BT, 2006-up FXD
10-0487	39965-99	36	Chain Guide 1999-05
9954-5	68042-99	37	Sensor Cover Screw Set
10-0814	25533-99A	38	Sprocket Retention Bolt Washer 1999-05
10-0920	25566-06	38	As Above 2006-up



Crank Sensor fits 1999-up TC-88.
VT No. 32-0988



Left Bearing Kit fits 2003-up TC-88 left side crank shaft.
VT No. 12-1544



Chrome Crank Sensor Cover Includes mount screw. 1999-up FXD-FLT.
VT No. 42-0953



Chrome Gear Cover for all TC-88 Big Twins models.

VT No.	Years
42-0702	2001-up
10-0813	1999-00 FLT, FXD 2000 FXST